



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



N667  
NMN000607546

Site Name: Section 25 Mine - NM0018

CERCLIS ID#: N/A

Alias Site Name: Homestake Sapin No. 25

Address: Latitude 35 degrees 24'51.56" Longitude 107 degrees 51'01.67"

City/County or Parish/State/Zip: McKinley County, New Mexico

Report Type: Pre-CERCLIS Screening

Date: 10/31/11

Author: NMED

**RECOMMENDATION:**

<input checked="" type="checkbox"/> 1. No Further Remedial Action Planned Under Superfund (NFRAP)	<input type="checkbox"/> 2. Further Investigation Needed Under Superfund												
	<table><tr><td><input type="checkbox"/> PA</td><td><input type="checkbox"/> HRS</td><td>Priority: <input type="checkbox"/> High</td></tr><tr><td><input type="checkbox"/> SI</td><td><input type="checkbox"/> RI/FS</td><td><input type="checkbox"/> Low</td></tr><tr><td><input type="checkbox"/> ESI</td><td><input type="checkbox"/> RA</td><td></td></tr><tr><td><input type="checkbox"/> Other: _____</td><td></td><td></td></tr></table>	<input type="checkbox"/> PA	<input type="checkbox"/> HRS	Priority: <input type="checkbox"/> High	<input type="checkbox"/> SI	<input type="checkbox"/> RI/FS	<input type="checkbox"/> Low	<input type="checkbox"/> ESI	<input type="checkbox"/> RA		<input type="checkbox"/> Other: _____		
<input type="checkbox"/> PA	<input type="checkbox"/> HRS	Priority: <input type="checkbox"/> High											
<input type="checkbox"/> SI	<input type="checkbox"/> RI/FS	<input type="checkbox"/> Low											
<input type="checkbox"/> ESI	<input type="checkbox"/> RA												
<input type="checkbox"/> Other: _____													
<input type="checkbox"/> 3. Action Deferred to: <input type="checkbox"/> RCRA <input type="checkbox"/> NRC <input type="checkbox"/> BLM													
<input type="checkbox"/> 4. Site Being Addressed Under the State Voluntary Cleanup Program (VCP): <input type="checkbox"/> Yes <input type="checkbox"/> No													
To be performed by: _____													

**NOTIFY AUTHORITY:**

<input type="checkbox"/> Removal	<input type="checkbox"/> RCRA	<input type="checkbox"/> TSCA	<input type="checkbox"/> CAA	<input type="checkbox"/> SMCRA
<input type="checkbox"/> Remedial	<input checked="" type="checkbox"/> State/Tribe	<input type="checkbox"/> NPDES	<input type="checkbox"/> NRC	<input type="checkbox"/> Resource Trustee: _____
<input type="checkbox"/> CERCLA Enforcement	<input type="checkbox"/> Federal Facility	<input type="checkbox"/> UIC	<input type="checkbox"/> SPCC	<input type="checkbox"/> Other: _____
SEND SSSR COPIES TO: <input type="checkbox"/> 6SF-AC <input type="checkbox"/> 6WQ-SP <input type="checkbox"/> ATSDR <input checked="" type="checkbox"/> State Agency <input type="checkbox"/> Tribal Agency				

**DISCUSSION:**

The New Mexico Environment Department (NMED) used operational history to develop a pre-CERCLIS screen for the Section 25 Mine site. The mine operated as a wet mine and records indicate that during mine operations, solution mining occurred (i.e., mine water was recirculated through the mine to further leach uranium). The surface facilities and main shaft are located on approximately 115 acres of disturbed surface on Section 23 and the underground workings are located within the section.

The mine site has been released from further requirements of the Mining Act Reclamation Program, but investigation into the impacts from the discharge of mine water and solution mining is being required pursuant to the New Mexico Water Quality Control Commission regulations.

NMED recommended that no further action be taken under CERCLA at the Section 25 Mine site due to on-going remedial activities pursuant to New Mexico regulations. EPA concurs with this recommendation.



**APPROVALS:**

<b>Report Reviewed by:</b>	<u>LaDonna Turner</u> (Site Assessment Manager)	<b>Signature:</b>	<u>LaDonna Turner</u>	<b>Date:</b>	<u>                    </u>
<b>Disposition Approved by:</b>	<u>Chris Villarreal</u> (Section Chief 6SF-TR)	<b>Signature:</b>	<u>Chris Villarreal</u>	<b>Date:</b>	<u>8/2/2013</u>